

Figure E.33 Time Step of Surface Corrosion for 1.0% Chloride Pre-Cracked Specimens




Figure E.34 Time Step of Rib Loss for 1.0% Chloride Pre-Cracked Specimens